

REPORT

TRUESDAIL LABORATORIES, INC.



CHEMISTS · MICROBIOLOGISTS · ENGINEERS
RESEARCH · DEVELOPMENT · TESTING
ESTABLISHED 1931

14201 FRANKLIN AVENUE
TUSTIN, CALIF. 92680
(714) 730-6239 • (213) 225-1564
FAX (714) 730-6462

CLIENT: Douglas Aircraft Company
Internal Mail Code C6-59
19503 South Normandie Ave.
Torrance, CA 90502
ATTN: Boramy Ith

REPORT DATE: July 14, 1994

RECEIVED: July 7, 1994

LABORATORY NUMBER: 69730

Water from Stormdrain, Torrance Facility
P.O. No: T & M 25998C


Second Quarter, 1994, Analysis as Required by NPDES Permit #CA0001414

RESULTS

Total Flow, GPD	No Flow
Temperature, °F	68
pH, Units (EPA 150.1)	8.0

Parameter	Method	MILLIGRAMS PER LITER Detection Limit	Concentration
Biochemical Oxygen Demand	405.1	2.0	ND
Chromium	200.7	0.01	ND
Oil and Grease	413.1	6.0	11.4
Settleable Solids (ml/L/hr)	160.5	0.20	ND
Total Suspended Solids	160.2	4.0	10.0

*ND = Not detected, below detection limit



Respectfully Submitted,
Truesdail Laboratories, Inc.


Thomas Herrin, Manager
Environmental Field Services

This report applies only to the samples investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.